




SIMILAR TO LEFT SIDE ASSEMBLY

- ① HAS ONE $\frac{1}{8}$ " SPACER BETWEEN MOUNTING DISC & FRAME (NEED TWO LEFT SIDE SHOULD PROBABLY HAVE $\frac{1}{8}$ " SPACERS INSTEAD OF TWO $\frac{1}{16}$ SPACERS @ EACH MOUNTING BOLT,
- ② ONE BEVELED WASHER MISSING FROM ASS'Y ARM - REPLACE WITH FLAT WASHER.
- ③ ALL FRICTION SURFACES ARE BARE STEEL; OTHERWISE PAINT ARMS / BRACKETS / SPRINGS BLACK